



CAIR and CAMR Training Workshop Atlanta, Georgia

March 15, 2007

8:30 a.m.	Introduction	Beverly Banister APTMD Division Director EPA Region 4
9:00 a.m.	CAIR/CAMR Update	Beth Murray
9:15 a.m.	CAIR/CAMR: Designated Representative and Establishing Allowance Accounts	Mary Shellabarger
9:45 a.m.	General Monitoring Requirements and Options	Louis Nichols
10:30 a.m.	<i>Break</i>	
10:45 a.m.	Ongoing Quality Assurance for NO _x and SO ₂ CEMS	Matthew Boze
12:00 p.m.	<i>Lunch</i>	
1:15 p.m.	LME Monitoring Option	Charlie Frushour
1:45 p.m.	Common Monitoring and Reporting Errors	Louis Nichols
2:15 p.m.	CAIR/CAMR: Annual Reconciliation	Mary Shellabarger
3:00 p.m.	<i>Break</i>	
3:15 p.m.	Mercury Monitoring Options and Requirements	Matt Boze and Charlie Frushour
4:30 p.m.	<i>Workshop Concludes</i>	